



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 1 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-4838	GROUP	ALL	INTENT TO CONTRACT OUT ETOPS <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON UNION HOLD CURRENTLY ON JOINT HOLD</i>	DEADLOCKED
SWA-4980	ERIC WATTS	BWI	OVERTIME BYPASS <i>CURRENTLY ON UNION HOLD CURRENTLY ON JOINT HOLD</i>	WITHDRAWN
SWA-5070	LARRY DILDINE	DAL	CROSS UTILIZATION OF THE INSPECTION WORKGROUP <i>CURRENTLY ON UNION HOLD CURRENTLY ON JOINT HOLD</i>	DEADLOCKED
SWA-5118	GROUP GSE	DAL	OUTSOURCING VIOLATION (TUG WIRE HARNESSSES) <i>CURRENTLY ON UNION HOLD CURRENTLY ON COMPANY HOLD</i>	WITHDRAWN W/O PREJUDICE
SWA-5119	GROUP GSE	DAL	CROSSUTILIZATION VIOLATION (REFURB SHOP DOING GSE SHOP WORK) <i>CURRENTLY ON UNION HOLD CURRENTLY ON COMPANY HOLD</i>	WITHDRAWN W/O PREJUDICE
SWA-5120	GROUP GSE	DAL	CROSSUTILIZATION VIOLATION (BWI STATION ACCOMPLISHING REFURB SHOP WORK) <i>CURRENTLY ON UNION HOLD CURRENTLY ON COMPANY HOLD</i>	WITHDRAWN W/O PREJUDICE
SWA-5127	FRED BISHOP	PHX	IMPROPER DENIAL FOR BUMP UP LEAD <i>CURRENTLY ON COMPANY HOLD</i>	JOINT HOLD
SWA-5128	TOM STEPHENSON	PHX	IMPROPER DENIAL FOR BUMP UP LEAD <i>CURRENTLY ON COMPANY HOLD</i>	JOINT HOLD
SWA-5135	TONY GLASOE	DAL	DOWNLINE VIOLATION - KNOWN RII <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 2 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5140	GROUP AMT	DAL	OUTSOURCING VIOLATION - ESCAPE SLIDES <i>CURRENTLY ON UNION HOLD</i>	WITHDRAWN W/O PREJUDICE
SWA-5147	GROUP	ALL	NBR: 08913 REV: 07 POS: INSTALLATION OF MAGEE PLASTICS RETURN AIR GRILLES <i>CURRENTLY ON JOINT HOLD</i>	UNION HOLD
SWA-5155	GROUP	ALL	INSP-25EA-04249 CARGO COMPARTMENT LINER INSPECTION <i>CURRENTLY ON UNION HOLD</i>	WITHDRAWN
SWA-5210	GROUP	ALL	NBR: 08913 REV: 07 POS: INSTALLATION OF MAGEE PLASTICS RETURN AIR GRILLES <i>CURRENTLY ON JOINT HOLD</i>	UNION HOLD
SWA-5218	GROUP	ALL	MOD 7 151342 AFT CARGO SCUFF PLATE DENTS PERMENENT REPAIR <i>CURRENTLY ON UNION HOLD</i>	WITHDRAWN
SWA-5292	AARON HANSEN	SMF	VENDOR PERFORMED WORK WITHOUT CALLING O/T <i>CURRENTLY ON UNION HOLD</i>	WITHDRAWN
SWA-5295	DAN BURGESS	MDW	GRIEVANCE PROCEEDURE <i>CURRENTLY ON JOINT HOLD</i>	UNION HOLD
SWA-5303	CHRIS LEIDAHN	BWI	DOWNLINE VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	JOINT HOLD
SWA-5308	JOEY STRAZZANTE	TPA	GROUND OPS USING TAIL STAND TO SUPPORT AIRCRAFT <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-5309	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS. <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 3 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5310	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS. <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-5311	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS. <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-5312	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS. <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-5313	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS. <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-5314	GROUP HRON AMT/INSPECTOR	PHX	OUTSOURCE A/C N487 NOSE GEAR CORROSION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5315	AKI OSHIRO	PHX	CONTRACT MX ACCOMPLISHED AN MV2 A/C N217 THAT WAS NOT DUE <i>CURRENTLY ON COMPANY HOLD</i>	SETTLED PRIOR
SWA-5316	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5317	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5318	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5319	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 4 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5320	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5321	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5322	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5323	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5324	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5325	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5326	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5327	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5328	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5329	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 5 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5330	GROUP INSP	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5332	GROUP AMT	ALL	AC 934 DOUBLE ENGINE CHANGE AT MCI <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5351	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5368	GROUP AMT	ALL	757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5369	GROUP AMT	ALL	757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5370	GROUP AMT	ALL	757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5371	GROUP AMT	ALL	757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5372	GROUP AMT	ALL	757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5373	GROUP AMT	ALL	757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5374	GROUP AMT	ALL	757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 6 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5375	GROUP AMT	ALL	757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5376	GROUP AMT	ALL	757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5377	GROUP AMT	ALL	757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5378	GROUP AMT	ALL	757-643-010-01 REV: POS: SDI (HFEC) - EXTERNAL - LEFT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5379	GROUP AMT	ALL	757-643-010-02 REV: POS: SDI (HFEC) - EXTERNAL - RIGHT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5380	GROUP AMT	ALL	757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5381	GROUP AMT	ALL	757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5382	GROUP AMT	ALL	757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5383	GROUP AMT	ALL	757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	WITHDRAWN



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 7 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5384	GROUP AMT	ALL	757-645-000-01 REV: POS: DVI - EXTERNAL - LEFT UPPER WING PANEL STRINGERS	DEADLOCKED
SWA-5385	GROUP AMT	ALL	757-645-000-02 REV: POS: DVI - EXTERNAL - RIGHT UPPER WING PANEL STRINGERS	DEADLOCKED
SWA-5386	GROUP AMT	ALL	757-650-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5387	GROUP AMT	ALL	757-650-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5388	GROUP AMT	ALL	757-699-000-01 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - LEFT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAST ENER ATTACHMENTS	DEADLOCKED
SWA-5389	GROUP AMT	ALL	757-699-000-02 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - RIGHT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAS TENER ATTACHMENTS	DEADLOCKED
SWA-5390	GROUP AMT	ALL	757-701-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5391	GROUP AMT	ALL	757-701-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5392	GROUP AMT	ALL	757-702-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACH MENTS (DIRECTION 1)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 8 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5393	GROUP AMT	ALL	757-702-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTAC HMENTS (DIRECTION 1)	DEADLOCKED
SWA-5394	GROUP AMT	ALL	757-703-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5395	GROUP AMT	ALL	757-703-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING RIB 27, FRONT ANDREAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5396	GROUP AMT	ALL	757-703-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING RIB 27, FRONT ANDREAR SPAR TENSION FITTINGS	WITHDRAWN
SWA-5397	GROUP AMT	ALL	732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5398	GROUP AMT	ALL	08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5399	GROUP AMT	ALL	14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5400	GROUP AMT	ALL	12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5401	GROUP AMT	ALL	14090 REV: POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 9 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5402	GROUP AMT	ALL	757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5403	GROUP AMT	ALL	757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5404	GROUP AMT	ALL	14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	WITHDRAWN
SWA-5405	GROUP AMT	ALL	12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	WITHDRAWN
SWA-5406	GROUP AMT	ALL	MV2 CHECK AND ALL ASSOCIATED CARDS ATTACHED.	DEADLOCKED
SWA-5407	GROUP AMT	ALL	MV2 CHECK AND ALL ASSOCIATED CARDS ATTACHED.	DEADLOCKED
SWA-5408	GROUP AMT	ALL	MV2 CHECK AND ALL ASSOCIATED CARDS ATTACHED.	DEADLOCKED
SWA-5409	GROUP AMT	ALL	MV2 CHECK AND ALL ASSOCIATED CARDS ATTACHED.	DEADLOCKED
SWA-5410	GROUP AMT	ALL	MV2 CHECK AND ALL ASSOCIATED CARDS ATTACHED.	DEADLOCKED
SWA-5411	GROUP AMT	ALL	C CHECK OUTSOURCE VIOLATION 3HC1 AND ALL RELATED TASKS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 10 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5412	GROUP AMT	ALL	C CHECK OUTSOURCE VIOLATION HC2 AND ALL RELATED TASKS	DEADLOCKED
SWA-5413	GROUP AMT	ALL	C CHECK OUTSOURCE VIOLATION 2HC2 AND ALL RELATED TASKS	DEADLOCKED
SWA-5414	GROUP AMT	ALL	C CHECK OUTSOURCE VIOLATION 2HC2 AND ALL RELATED TASKS	DEADLOCKED
SWA-5415	GROUP AMT	ALL	732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5416	GROUP AMT	ALL	08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5417	GROUP AMT	ALL	08913 REV: 07 POS: INSTALLATION OF MAGEE PLASTICS RETURN AIR GRILLES	UNION HOLD
SWA-5418	GROUP AMT	ALL	14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5419	GROUP AMT	ALL	12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5420	GROUP AMT	ALL	14090 REV: POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 11 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5421	GROUP AMT	ALL	G456521 RT ENGINE INLET COWL LIP SKIN SPLICE, SEGMENT 1 LOWE R INBD CORNER HAS TWO PULLED EDGE FASTENERS	DEADLOCKED
SWA-5422	GROUP AMT	ALL	G456524 UPPER INBD SEGMENT 3 HAS TWO PULLED LIP SKIN SPLICE FASTENERS AND A PULLED 7TH FASTENERS BELOW THE SPLICE.	DEADLOCKED
SWA-5424	GROUP AMT	ALL	732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5425	GROUP AMT	ALL	757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5426	GROUP AMT	ALL	757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5427	GROUP AMT	ALL	08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5428	GROUP AMT	ALL	14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5429	GROUP AMT	ALL	12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5430	GROUP AMT	ALL	J752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHES	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 12 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5431	GROUP AMT	ALL	28438 REV: POS: FUSELAGE SKIN. JUST FWD OF STA. 540 HAS CRACK INDICATION IN BOTH AFT FASTENER HOLES, 2ND & 3RD ROWBELOW STRINGER 22R AND SURFACE CRACKS AT FWD FASTENER HOLE IN 3RD ROW. [AD DRIVEN, SI# 120	DEADLOCKED
SWA-5432	GROUP AMT	ALL	28440 REV: POS: FUSELAGE SKIN. JUST FWD OF STA. 540 HAS CRACK INDICATION IN AFT FASTENER HOLE, 2ND ROW BELOW STRINGER 22L. [AD DRIVEN, SI# 12042-53, STEP 2.A.(1)]	DEADLOCKED
SWA-5433	GROUP AMT	ALL	757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5434	GROUP AMT	ALL	757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5435	GROUP AMT	ALL	757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1)	DEADLOCKED
SWA-5436	GROUP AMT	ALL	757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1)	DEADLOCKED
SWA-5437	GROUP AMT	ALL	757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5438	GROUP AMT	ALL	757-613-000-01 REV: POS: SDI (LFEC) - INTERNAL - LEFT LOWER WING PANEL STRINGERS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 13 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5439	GROUP AMT	ALL	757-613-000-02 REV: POS: SDI (LFEC) - INTERNAL - RIGHT LOWER WING PANEL STRINGERS	DEADLOCKED
SWA-5440	GROUP AMT	ALL	757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5441	GROUP AMT	ALL	757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5442	GROUP AMT	ALL	757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5443	GROUP AMT	ALL	757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5444	GROUP AMT	ALL	757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5445	GROUP AMT	ALL	757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5446	GROUP AMT	ALL	757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5447	GROUP AMT	ALL	757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 14 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5448	GROUP AMT	ALL	757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5449	GROUP AMT	ALL	757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5450	GROUP AMT	ALL	757-643-010-01 REV: POS: SDI (HFEC) - EXTERNAL - LEFT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5451	GROUP AMT	ALL	757-643-010-02 REV: POS: SDI (HFEC) - EXTERNAL - RIGHT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5452	GROUP AMT	ALL	757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5453	GROUP AMT	ALL	757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA5454	GROUP AMT	ALL	757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA=5455	GROUP AMT	ALL	757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5456	GROUP AMT	ALL	757-645-000-01 REV: POS: DVI - EXTERNAL - LEFT UPPER WING PANEL	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 15 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5457	GROUP AMT	ALL	757-645-000-02 REV: POS: DVI - EXTERNAL - RIGHT UPPER WING PANEL	DEADLOCKED
SWA-5458	GROUP AMT	ALL	757-650-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5459	GROUP AMT	ALL	757-650-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5460	GROUP AMT	ALL	757-699-000-01 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - LEFT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAST ENER ATTACHMENTS	DEADLOCKED
SWA-5461	GROUP AMT	ALL	757-699-000-02 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - RIGHT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAS TENER ATTACHMENTS	DEADLOCKED
SWA-5462	GROUP AMT	ALL	757-701-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5463	GROUP AMT	ALL	757-701-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5464	GROUP AMT	ALL	757-702-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACH MENTS (DIRECTION 1)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 16 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5465	GROUP AMT	ALL	757-702-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS (DIRECTION 1)	DEADLOCKED
SWA-5466	GROUP AMT	ALL	757-702-001-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5467	GROUP AMT	ALL	757-702-001-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5468	GROUP AMT	ALL	757-703-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5469	GROUP AMT	ALL	757-703-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5470	JON SELBY	MCO	DOWNLINE BYPASS FOR NOSE LANDING GEAR CHANGE 3 AMT'S	SETTLED PRIOR
SWA-5471	GROUP PMX	DAL	BLENDED WORK VIOLATION DRYWALL WORK	WITHDRAWN
SWA-5472	GROUP PMX	DAL	BLENDED WORK VIOLATION INSULATION WORK	WITHDRAWN
SWA-5473	DAN BURGESS	MDW	O/T BYPASS	UNION HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 17 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5474	DAN BURGESS	MDW	SUPERVISOR PERFORMING COVERED WORK	UNION HOLD
SWA-5475	JOHN CHUPAK	MDW	DAYTRADE SUSPENSION DUE TO TRAINING	SETTLED PRIOR
SWA-5476	GROUP	ALL	732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5477	GROUP	ALL	08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5478	GROUP	ALL	14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5479	GROUP	ALL	12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5480	GROUP	ALL	G533437 LT ENGINE NOSE INLET COWL HAS 3 PULLED FASTENERS AT AROUND THE 2 O'CLOCK POSITION	DEADLOCKED
SWA-5481	GROUP	ALL	J752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHES	DEADLOCKED
SWA-5482	GROUP	ALL	14090 REV: 01 POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 18 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5483	GROUP	ALL	727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO-BACK ASSEMBLY	DEADLOCKED
SWA-5484	GROUP	ALL	J727-009-00-01REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES	DEADLOCKED
SWA-5485	GROUP	ALL	385525 #1 ENGINE INLET COWL HAS 2 LOOSE FASTENERS AT 10 O'C LOCK AND 2 O'CLOCK POSITION	DEADLOCKED
SWA-5486	GROUP	ALL	385526 #2 ENGINE INLET COWL HAS PULLED FASTENER AT THE 10 O 'CLOCK POSITION	DEADLOCKED
SWA-5487	GROUP	ALL	757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5488	GROUP	ALL	757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5489	GROUP	ALL	757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1)	DEADLOCKED
SWA-5490	GROUP	ALL	757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5491	GROUP	ALL	757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5492	GROUP	ALL	757-613-000-01 REV: POS: SDI (LFEC) - INTERNAL - LEFT LOWER WING PANEL STRINGERS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 19 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5493	GROUP	ALL	757-613-000-02 REV: POS: SDI (LFEC) - INTERNAL - RIGHT LOWER WING PANEL STRINGERS	DEADLOCKED
SWA-5494	GROUP	ALL	757-614-110-01 REV: POS: GVI - EXTERNAL - LEFT LOWER WING SKIN PANEL	DEADLOCKED
SWA-5495	GROUP	ALL	757-614-110-02 REV: POS: GVI - EXTERNAL - RIGHT LOWER WING SKIN PANEL	DEADLOCKED
SWA-5496	GROUP	ALL	757-614-130-01 REV: POS: GVI - EXTERNAL - LEFT LOWER WING PANEL SKIN	DEADLOCKED
SWA-5497	GROUP	ALL	757-614-130-02 REV: POS: GVI - EXTERNAL - RIGHT LOWER WING PANEL SKIN	DEADLOCKED
SWA-5498	GROUP	ALL	757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5499	GROUP	ALL	757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5500	GROUP	ALL	757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5501	GROUP	ALL	757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5502	GROUP	ALL	757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 20 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5503	GROUP	ALL	757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5504	GROUP	ALL	757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5505	GROUP	ALL	757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5506	GROUP	ALL	757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5507	GROUP	ALL	757-643-010-01 REV: POS: SDI (HFEC) - EXTERNAL - LEFT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5508	GROUP	ALL	757-643-010-02 REV: POS: SDI (HFEC) - EXTERNAL - RIGHT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5509	GROUP	ALL	757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5510	GROUP	ALL	757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5511	GROUP	ALL	757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 21 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5512	GROUP	ALL	757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5513	GROUP	ALL	757-645-000-01 REV: POS: DVI - EXTERNAL - LEFT UPPER WING PANEL	DEADLOCKED
SWA-5514	GROUP	ALL	757-645-000-02 REV: POS: DVI - EXTERNAL - RIGHT UPPER WING PANEL	DEADLOCKED
SWA-5515	GROUP	ALL	757-650-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5516	GROUP	ALL	757-650-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5517	GROUP	ALL	757-699-000-01 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - LEFT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAST ENER ATTACHMENTS	DEADLOCKED
SWA-5518	GROUP	ALL	757-699-000-02 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - RIGHT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAS TENER ATTACHMENTS	DEADLOCKED
SWA-5519	GROUP	ALL	757-701-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5520	GROUP	ALL	757-701-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING TENSION FITTINGS AT RIB 27	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 22 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5521	GROUP	ALL	757-702-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS (DIRECTION 1)	DEADLOCKED
SWA-5522	GROUP	ALL	757-702-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS (DIRECTION 1)	DEADLOCKED
SWA-5523	GROUP	ALL	757-702-001-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5524	GROUP	ALL	757-702-001-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5525	GROUP	ALL	757-703-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5526	GROUP	ALL	757-703-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5527	GROUP/AMT	DEN	MULTIPLE A/C OTS CREATING O/T BYPASS	DEADLOCKED
SWA-5528	GROUP/AMT	DEN	MULTIPLE A/C OTS CREATING O/T BYPASS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 23 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5529	GROUP PMX	DAL	OUTSOURCING VIOLATION – BREAK DOLLIES	SETTLED PRIOR
SWA-5530	GROUP PMX	DAL	OUTSOURCING VIOLATION – 45 TON JACKS	COMPANY HOLD
SWA-5531	GROUP PMX	DAL	OUTSOURCING VIOLATION – BREAK DOLLIES	SETTLED PRIOR
SWA-5532	GROUP PMX	DAL	OUTSOURCING VIOLATION – 25 TON JACK	COMPANY HOLD
SWA-5533	GROUP PMX	DAL	OUTSOURCING VIOLATION – 50 TON JACKS	COMPANY HOLD
SWA-5534	RUSSELL PINSON	PHX	DOWNLINE BYPASS	SETTLED PRIOR
SWA-5537	JAMES OLIVER	MDW	PERSONNEL SAFTEY	UNION HOLD
SWA-5538	TERRY ARNOLD	MDW	SUPERVISOR PERFORMING COVERED WORK	SETTLED PRIOR
SWA-5539	TERRY ARNOLD	MDW	SUPERVISOR PERFORMING COVERED WORK	UNION HOLD
SWA-5540	LARRY LARA	BWI	SUPERVISOR PERFORMING COVERED WORK	UNION HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 24 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5541	GROUP	ALL	732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5542	GROUP	ALL	08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5543	GROUP	ALL	14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5544	GROUP	ALL	12246 REV: 02 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5545	GROUP	ALL	14090 REV: 01 POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED
SWA-5546	GROUP	ALL	J727-009-00-01 REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES	DEADLOCKED
SWA-5547	GROUP	ALL	727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO-BACK ASSEMBLY	DEADLOCKED
SWA-5548	GROUP	ALL	757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5549	GROUP	ALL	757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 25 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5550	GROUP	ALL	757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5551	GROUP	ALL	757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5552	GROUP	ALL	757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5553	GROUP	ALL	757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5554	GROUP	ALL	757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5555	GROUP	ALL	757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5556	GROUP	ALL	757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5557	GROUP	ALL	757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5558	GROUP	ALL	757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5559	GROUP	ALL	757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 26 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5560	GROUP	ALL	757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5561	GROUP	ALL	757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5562	GROUP	ALL	757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5563	GROUP	ALL	757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5564	GROUP	ALL	757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5565	GROUP	ALL	757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5566	JASON GOODMAN	DAL	OVERTIME BYPASS RESULTING FROM PAID ADMINISTRATIVE LEAVE	WITHDRAWN W/O PREJUDICE
SWA-5567	GROUP AMT	DAL	IDLING OF HEAVY MAINTENANCE LINE	DEADLOCKED
SWA-5568	BRIAN HEEG	DAL	DISCIPLINE RESULTING IN LOSS OF PAY WITHOUT FACT FINDING	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 27 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5570	GROUP	ALL	D283278, APU SERVICE DOOR HAS DAMAGED AREA 5IN LEFT FWD CORNER, DAMGED AREA IS 4IN LONG X 1IN WIDE ON EDGE OF DOOR. C/W REPAIR-52EA-05218 PERMANENT REPAIR DUE WITHIN 10 DAYS. UPDATE THE PERMANENT REPAIR LIMIT TO 10DAYS FROM THE ORIGINAL REPORT DATE (5/19/18). (REF SA-M 735/ERIC WATTENBARGER) (MX NOTE) <u>COMPANY FAILED TO MEET TIMELINES</u>	DEADLOCKED
SWA-5571	RUI LEONARDO	LAS	DENIED TRAINING IN DALLAS AS NOT IN HIS ZONE	UNION HOLD
SWA-5572	GROUP	ALL	732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5573	GROUP	ALL	757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5574	GROUP	ALL	757-643-100-01 REV: POS: SDI - (UT) - LEFT SKIN AT NACELLE SUPPORT FITTING ATTACHMENTS	WITHDRAWN
SWA-5575	GROUP	ALL	757-643-100-02 REV: POS: SDI - (UT) - RIGHT SKIN AT NACELLE SUPPPORT FITTING ATTACHMENTS	WITHDRAWN



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 28 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5576	GROUP	ALL	757-643-101-01 REV: POS: SDI (HFEC) - LEFT SKIN AT NACELLE SUPPORT FITTING ATTACHMENTS	WITHDRAWN
SWA-5577	GROUP	ALL	757-643-101-02 REV: POS: SDI (HFEC) - RIGHT SKIN AT NACELLE SUPPORT FITTING ATTACHMENTS	WITHDRAWN
SWA-5578	GROUP	ALL	08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5579	GROUP	ALL	14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5580	GROUP	ALL	12246 REV: 02 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5581	GROUP	ALL	14090 REV: 01 POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED
SWA-5582	GROUP	ALL	171435 DURING LIGHTNING STRIKE EXTERNAL DAMAGE INSPEC FOUND GAUGE IN VERTICAL STAD FWD DORSAL FIN FARRING LH SI DE .450 IN X .030 IN	WITHDRAWN
SWA-5583	GROUP	ALL	538185 #1 ENG INLET LIP SKIN OUTER RIVITS PULLED/LOOSE 2 AT 1030, 2 AT 530, B BETWEEN 600 AND 700	WITHDRAWN



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 29 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5584	GROUP	ALL	538186 #2 ENG INLET LIP SKIN OUTER RIVITS PULLED/LOOSE 1 AT 200 2 AT 700.	WITHDRAWN
SWA-5585	GROUP	ALL	757-614-130-01 REV: POS: GVI - EXTERNAL - LEFT LOWER WING PANEL SKIN	DEADLOCKED
SWA-5586	GROUP	ALL	757-614-130-02 REV: POS: GVI - EXTERNAL - RIGHT LOWER WING PANEL SKIN	DEADLOCKED
SWA-5587	GROUP	ALL	757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5588	GROUP	ALL	727-41-02 REV: POS: REM/REP - STABILIZER JACKSCREW ASSEMBLY	JOINT HOLD
SWA-5589	GROUP	ALL	727-41-03 REV: POS: REM/INST - HORIZONTAL STABILIZER TRIM CONTROL CABLES	JOINT HOLD
SWA-5590	GROUP	ALL	727-41-04 REV: POS: DVI - STABILIZER TRIM BALLSCREW, BALLNUT, RETURN TUBES AND UPPER AND LOWER GIMBAL PINS	JOINT HOLD
SWA-5591	GROUP	ALL	727-41-05 REV: POS: LUB - STABILIZER TRIM ACTUATOR AND ACTUATOR GIMBAL PINS	JOINT HOLD
SWA-5592	GROUP	ALL	J9363583 SI#:0270200 DESC: JACKSCREW STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN: 251A4510-6 MSN: KE00372 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED	JOINT HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 30 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5593	GROUP	ALL	28840 REV: POS: WHILE PERFORMING THE 540 LOWER BULKHEAD CHORD INSPECTION ON THE LEFT HAND SIDE, HFEC INDICATED A CRACK IN THE AFT HOLE ON THE SECOND ROW FROM THE TOP	DEADLOCKED
SWA-5594	GROUP	ALL	J727-009-00-01 REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES	DEADLOCKED
SWA-5595	GROUP	ALL	08915 REV: POS: RESTORATION OF ANTI-STATIC COATING COMMON TO THE AILERON FAIRINGS FASTENERS	WITHDRAWN
SWA-5596	GROUP	ALL	#1 ENGINE INLET COWL HAS LOOSE INLET FASTENERS. THERE ARE 4 LOOSE FASTENERS AT THE 5 O'CLOCK POSITION, 1 LOOSE FASTENER AT THE 6 O'CLOCK POSITION AND 4 LOOSE FASTENERS AT THE 7 O'CLOCK POSITION	DEADLOCKED
SWA-5597	GROUP	ALL	08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5598	GROUP	ALL	E14084 03 MOD TYPE: E NBR: 14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5599	GROUP	ALL	12246 REV: 02 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 31 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5600	GROUP	ALL	D169130 #2 INLET HAS 2EA LOOSE FASTENERS AT 2 O'CLOCK POSITION AT SPLICE ON OUTER ROW LIP SKIN. D169131 TRANSFERED FROM MX ACTION LOG PAGE 0013330. #2 ENG I NLET COWL LIP SKIN HAS LOOSE FASTENERS, 1 @ 2 O'CLOCK AND 2 @ 10 O'CLOCK.	DEADLOCKED
SWA-5601	GROUP	ALL	727-41-02 REV: POS: REM/REP - STABILIZER JACKSCREW ASSEMBLY	JOINT HOLD
SWA-5602	GROUP	ALL	727-41-03 REV: POS: REM/INST - HORIZONTAL STABILIZER TRIM CONTROL CABLES	JOINT HOLD
SWA-5603	GROUP	ALL	727-41-04 REV: POS: DVI - STABILIZER TRIM BALLSCREW, BALLNUT, RETURN TUBES AND UPPER AND LOWER GIMBAL PINS	JOINT HOLD
SWA-5604	GROUP	ALL	727-41-05 REV: POS: LUB - STABILIZER TRIM ACTUATOR AND ACTUATOR GIMBAL PINS	JOINT HOLD
SWA-5605	GROUP	ALL	727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO-BACK ASSEMBLY	DEADLOCKED
SWA-5606	GROUP	ALL	J727-009-00-01 REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES	DEADLOCKED
SWA-5607	DAN BURGESS	MDW	OVERTIME BYPASS	SETTLED PRIOR
SWA-5608	DAN BURGESS	MDW	OVERTIME BYPASS	SETTLED PRIOR



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 32 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5609	DAN BURGESS	MDW	OVERTIME BYPASS	SETTLED PRIOR
SWA-5610	GROUP	MDW	DOWNLINE VIOLATION	SETTLED PRIOR
SWA-5611	TERRY ARNOLD	MDW	OVERTIME BYPASS	SETTLED PRIOR
SWA-5612	TERRY ARNOLD	MDW	OVERTIME BYPASS	SETTLED PRIOR
SWA-5613	TERRY ARNOLD	MDW	OVERTIME BYPASS	WITHDRAWN
SWA-5614	DAN BURGESS	MDW	SHIFT START TIME CHANGE	UNION HOLD
SWA-5615	STEVE PRETTO	MDW	DOWNLINE VIOLATION	UNION HOLD
SWA-5616	GROUP	LAS	INCORRECT DOWNLINE LIST CAUSING BYPASSES	COMPANY HOLD
SWA-5617	GROUP	DAL	TRAINING NON-COMPLIANCE LOCKOUT	DEADLOCKED
SWA-5618	ASHENAFI NEGUSSIE	DAL	UNJUST PUNISHMENT / DISCIPLINE VIOLATION	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

JULY 11, 2018

Page: 33 of 33

DCASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5619	MIKE MULLINS	DAL	UNJUST PUNISHMENT / DISCIPLINE VIOLATION	UNION HOLD
SWA-5621	STEVE PRETTO	MDW	OVERTIME CALLOUT PROCEDURE	UNION HOLD
SWA-5622	DAN BURGESS	MDW	PERFORMING WORK OF OTHER COVERED GROUP	UNION HOLD

7/16/2018 11:08 AM